

# SOUTH PRODUCTION NOTES

May 10, 2016  
7-3 Shift Notes

**BASF EMPLOYEES**

165 Last Recordable

232 Last Lost time

**Title V Notes:** Trimer is down due to a leak. Lucas starting on repairs; expected to take around 6 days including cure time. Trimer has been locked out.

F1-Is the F1 Work complete?? If so it needs to be unlocked.

CTO – is online and running.

Sly Scrubber – Need to perform PM sampling once a day (2<sup>nd</sup> shift) when running.

## **#1 MED / X-253 Next:**

MED portion of the clean up is complete.

## **#1 RC / X-253 Next:**

Started cleaning for X253 next. Will need a 4 mesh screen for the granulator.

## **#2 MED line / Styrene:**

4 batches have been completed. Holding for further instructions. Page will need to modify the valve to move from blocking the injectors.

Green drums are the only drums to have dry ice put into them. Only the Green drums vent outward.

## **#2 RC / Clean for Styrene:**

Continue cleaning. Ready to run sand through after sock is put on. Can not get the syntron to start up until the F1 Scrubber is unlocked.

## **#3 MED line / D1717 NAQ:**

Finished batch 130 on midnights. Continue holding for now until Bodmann determines if we have enough material.

**Make sure we are greasing end seals once per shift when running.**

## **#3 RC / D1717 NAQ:**

Continue to run. Need to get to Lot 5 Bag 12 to meet order requirements.

## **#4 RC / Selexorb:**

Currently on hold due to Trimer repair. Need to keep a close eye on temps and feed rate as we have been chasing them.

### **#5 RC / Cleaning for Catoxid:**

Continue with cleanup.

GEM has dropped the feed end rotolock and will be replacing the tube gaskets on Tuesday. **Need to check if Vacuumax is clogged.**

Thermowell was removed.

**FYI – New interlocks are in place for the feed screw - See MOD for interlock instructions.**

When running, feed Hopper should not be filled past 2 feet below the top to allow room for blowdowns. HEPA filter was last changed out 4-1-16 on afternoon shift.

### **#6 RC & Dryer / D-0257:**

Continue to feed. Do not use new Blue buggies. Okay to use scale in bldg 27 for check weighing.

### **West Pfaudler / D-0222:**

Ok to restart per engineer.

Lot 192,193,194,195, and **196** are all in pass and are ok to use.

The steam repairs are done. Set to 30.

### **East Pfaudler/ D-0257:**

Continue running. pH probe is broken. Need to use the one in building 27 until we can get another one. Raws are on the back dock.

Don't use the blue buggies.

### **6 Tank: D-0222 solution:**

Do not make a tank, hold for engineering approval.

### **7 Tank: D-0222 Solution:**

Tank was adjusted on second shift Monday night. Ok to start. Had issues with temp control on nights. Watch closely.

### **National Dryer / D-0222:**

Feed as material is available.

### **PK Blender / Catoxid next:**

Ok to start up. Staged raws on midnights. May be making a batch late on shift. Page switched out the discharge plate and installed a removable extension so that we can switch between totes and bags ourselves.

DP Gauge should be set at 3.5 and 4.25.

### **Abbe Blender / D 5206:**

HF tote has been closed up and Abbe lid was removed and vessel cleaned out. Cover plates over open hole in floor have been reinstalled.

**Tower 3 / DPT 0101:**

Need to vibrate down tower. Can load when manpower permits but do not start.

**Tower 6 / DPT 0101 :**

Tower is started up on second shift. Continue.

**North Screener / Cu-1155:**

Screener is set up for Cu-1155. Holding for engineering

**South Screener / Cu 0860:**

Scale repaired, continue to run. If you wash down drums with water you need to dry them off – the green drums are very prone to rust.

**#2662 (west) Pill Machine / AI 3915:**

Continue as manpower permits. Next bags to be processed will be the bags from the North end.

**#2664 (east) Pill Machine /**

Has been taken down to maintenance for inspection by rewiring company.

**TK #2 / Zr-0404:**

Done. Blowers have been turned off and kiln is down.  
Leave the saggars on - we don't know what product we will be going to next.

**TK #4 / X-540:**

Unloading complete and gas shut off.

**Harrop Kiln / AI-3920 next:**

Continue to run. Use latest material off the pill machine.  
We will need to start running product from the north end to get quality back on it.

**Building 27 Belt Filter / Cu 6081:**

Continue to run as manpower allows.  
We have switched to 188 lined super sacks. These will need cardboard sleeves around them and new clean pallets.

**PRIORITIES:**



- 1) #6RC/East Pfaudler
- 2) #2 RC South Cu-0360 T then change over
- 3) West Pfaudler/National Dryer
- 4) #4 RC/Trimer
- 5) #3 MED/RC/CTO
- 6) #1 MED/RC
- 7) Clean-up & change over #2 MED
- 8) Re-screening of E-403 TU
- 9) South PK
- 10) #5 RC
- 11) Horne Machine
- 12) Reduction Towers/Screening
- 13) North PK/Wsyssmont
- 14) Kneader
- 15) PR2 Cu-0864 T
- 16) PR2 Al-3915 T
- 17) Harrop Kiln
- 18) #2 RC North